Mercedes-Benz

48107764

Mercedes Benz at Long of Chattanooga
6039 International Drive
Chattanooga, TN 37421
(423) 855-3726
http://www.longco.mercedesdealer.com/
Scanned by: Mercedes Service

| | | |
|---|---|---|
| VIN | - Not Captured - | |
| Vehicle | - Unknown - | |
| License Plate | TDN7877 - TN | Odo: mi. |

## Vehicle Scan Summary · 10/3/2024, 1:50 PM

**Scan Result**

**Possible Service**

**Diagnostic Notes**

## Braking Distance

( 70 MPH - Wet Surface )




### Left Front Tire

OUTSIDE — INSIDE




Groove Depth in **32nds**

DOT: Size: Load:

Notes:

- Check for minor inside wear on this tire. Consider a wheel alignment. See your service advisor.
- The sample collected for this tire indicates the Tread Depth is safe, replacement not needed today. See your service advisor.

### Right Front Tire

INSIDE — OUTSIDE




Groove Depth in **32nds**

DOT: Size: Load:

Notes:

- Check for abnormal tire wear. See your service advisor.
- This tire has shoulder wear. Usually caused by tire pressure under inflation.
- The sample collected for this tire indicates the Tread Depth is minimal and replacement is

### Left Rear Tire

OUTSIDE — INSIDE




Groove Depth in **32nds**

DOT: Size: Load:

Notes:

- Check for accelerated inside wear on this tire. Consider a wheel alignment. See your service advisor.
- The sample collected for this tire indicates the Tread Depth is safe and is like new.

### Right Rear Tire

INSIDE — OUTSIDE




Groove Depth in **32nds**

DOT: Size: Load:

Notes:

- Check for abnormal tire wear. See your service advisor.
- The sample collected for this tire indicates the Tread Depth is safe, replacement not needed today. See your service advisor.

GOOD | MARGINAL | REPLACE SOON | REPLACE NOW