



Mercedes-Benz

Mercedes Benz at Long of Chattanooga
6039 International Drive
Chattanooga, TN 37421
(423) 855-3726
<http://www.longco.mercedesdealer.com/>
Scanned by: Mercedes Service




52595466

VIN	- Not Captured -	
Vehicle	- Unknown -	
License Plate	BDB9619 - TN	Odo: mi.

Vehicle Scan Summary · 8/8/2025, 11:46 AM

Scan Result



Possible Service




Diagnostic Notes



Braking Distance


(70 MPH - Wet Surface)



Shorter is Safer!

■ Your Tires

■ New Tires




3.1 4.6 4.1 3.7

Groove Depth in 32nds

DOT: Size: Load:

Notes:

- Check for abnormal tire wear. See your service advisor.
- Check for accelerated outside wear on this tire. Consider a wheel alignment. See your service advisor.




4.0 4.5 4.5 2.8

Groove Depth in 32nds

DOT: Size: Load:

Notes:

- Check for accelerated outside wear on this tire. Consider a wheel alignment. See your service advisor.
- The sample collected for this tire indicates the Tread Depth is NOT safe. Replacement is recommended today. See your service advisor.




5.5 5.1 5.4 5.8

Groove Depth in 32nds

DOT: Size: Load:

Notes:

- The sample collected for this tire indicates the Tread Depth is safe, replacement not needed today. See your service advisor.



6.1 5.3 5.2 5.4

Groove Depth in 32nds

DOT: Size: Load:

Notes:

- The sample collected for this tire indicates the Tread Depth is safe, replacement not needed today. See your service advisor.

GOOD

MARGINAL

REPLACE SOON

REPLACE NOW